

United States of America
Department of Transportation — Federal Aviation Administration
Supplemental Type Certificate

Number

SA7240SW-D

This certificate, issued to

Dassault Falcon Jet
P.O. Box 967
Little Rock, Arkansas 72203

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product — Type Certificate Number:

A46EU

Make:

Dassault Aviation

Model:

Falcon 900

Description of Type Design Change:

Installation of the Standby Instrument System in accordance with Drawing List Report No. F90-01040 Revision V dated 11-2-00, or later FAA approved revision.

Limitations and Conditions:

Compatibility of this modification with other previously approved modifications must be determined by the installer.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application:

March 25, 1988

Date reissued:

Date of issuance:

August 4, 1988

Date amended:

See Page 2

Rev. 7



By direction of the Administrator

Joseph F. Coerke
Andrew A. Boersma (Signature)
DAS8SW COORDINATOR

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.

United States of America
Department of Transportation—Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

Number SA7240SW-D

Date Amended: 1-23-89, 8-1-89, 12-13-90, 9-9-91, 4-6-92, 10-27-92, 11-6-00, Rev 7

Description of Type Design Change:

- 1) FAA Approved Airplane Flight Manual Supplement, Report No. 36057-1, Revision A, dated 8-1-89, or later approved revision is required (when -501 installation is used).
- 2) FAA Approved Airplane Flight Manual Supplement, Report No. 36057-2, Revision A, dated 8-7-91, or later approved revision is required (when -503 installation is used).
- 3) FAA Approved Airplane Maintenance Manual Supplement, Report No. 36606, Revision NC, dated 6-30-99, or later approved revision is required (when -507 installation is used).

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

INSTRUCTIONS: The transfer endorsement below may be used to notify the appropriate FAA Regional Office of the transfer of this Supplemental Type Certificate.

The FAA will reissue the certificate in the name of the transferee and forward it to him.

TRANSFER ENDORSEMENT

Transfer the ownership of Supplemental Type Certificate Number _____

to *(Name of transferee)* _____

(Address of transferee) _____
(Number and street)

(City, State, and ZIP code)

from *(Name of grantor)* *(Print or type)* _____

(Address of grantor) _____
(Number and street)

(City, State, and ZIP code)

Extent of Authority (if licensing agreement): _____

Date of Transfer: _____

Signature of grantor *(In ink)*: _____